

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOCORAPHS

Obadiah Smith House  
853 St. Johnland Rd., San Remo  
Smithtown  
Suffolk County  
New York

Jack Boucher, Photographer, 1963

NY-6110-1	CENERAL VIEW OF SOUTH (FRONT) ELEVATION IN WINTER
NY-6110-2	CENERAL VIEW OF SOUTH (FRONT) ELEVATION IN SUMMER
NY-6110-3	OBLIQUE VIEW OF SOUTH FRONT IN WINTER, WITHOUT PORCH
NY-6110-4	OBLIQUE VIEW OF SOUTH FRONT IN SUMMER, WITH WOODEN PORCH
NY-6110-5	EAST (END) ELEVATION
NY-6110-6	OBLIQUE VIEW OF NORTH (REAR) ELEVATION
NY-6110-7	DETAIL OF SOUTH (FRONT) ENTRANCE
NY-6110-8	INTERIOR, SECOND FLOOR, SOUTHEAST BEDROOM, DETAIL OF TIMBER FRAMING
NY-6110-9	INTERIOR, FIRST FLOOR, KITCHEN, DETAIL OF FIREPLACE WITH BRICK, ARCHED BAKE OVEN
NY-6110-10	INTERIOR, SECOND FLOOR, SOUTHWEST BEDROOM, DETAIL OF FIREPLACE
NY-6110-11	INTERIOR, SECOND FLOOR, NORTHWEST BEDROOM, GENERAL VIEW OF FIREPLACE, FIREPLACE IN SOUTHWEST BEDROOM VISIBLE THROUGH DOORWAY
NY-6110-12	INTERIOR, SECOND FLOOR, NORTHWEST CORNER OF SOUTHEAST BEDROOM, DETAIL OF CORNER CUPBOARD
NY-6110-13	INTERIOR, SECOND FLOOR, NORTHWEST CORNER OF SOUTHEAST BEDROOM, DETAIL OF CORNER CUPBOARD WITH DOORS OPEN
NY-6110-14	INTERIOR, SECOND FLOOR, CENTER BEDROOM, EXPOSED SOUTH WALL, SHOWING BACK SIDE OF CORNER CUPBOARD

Obadiah Smith House  
HABS No. NY-6110  
Index to Photographs  
p. 2

- NY-6110-15      INTERIOR, SECOND FLOOR, CENTER BEDROOM, CLOSE-UP DETAIL OF  
                     EXPOSED BACK SIDE OF CORNER CUPBOARD
- NY-6110-16      INTERIOR, FIRST FLOOR, ENTRANCE HALL, DETAIL OF LANDING  
                     OF WINDING STAIR
- NY-6110-17      INTERIOR, DETAIL OF TIMBER FLOOR JOISTS
- NY-6110-18      INTERIOR, DETAIL OF TIMBER WALL FRAMING
- NY-6110-19      INTERIOR, DETAIL OF WALL WITH PLASTER REMOVED, EXPOSING  
                     FRAMING